

RR / R2 LINEAR LIGHTS

FIRMWARE RELEASE NOTES

V0.8B - starCTRL Release - 2023-2-26

Improvements:

1. Paperazzi effect now flashes a 4x larger flash for 4x longer, with a wider range of rates

Bug Fixes

- 2. Resolved DMX address above Address 256 does not respond correctly.
- 3. StarCTRL is now disabled when using the wireless shortcut to turn off wireless
- 4. StarCTRL now correctly receives the fixture name on first connection
- 5. StarCTRL now is only able to be enabled when the CRMX module has the correct firmware or later (1.0.5.1)
- 6. Fixed status LED issue that would occasionally cause random incorrect colors
- 7. Fixed issue with WIFI staying in AP mode when wireless is not in WIFI
- 8. Fixed issue with WIFI attempting to connect to invalid AP SSIDs

V0.8A - starCTRL Release - 2023-1-19

New Features

1. New Mode - startCTRL for enabling Bluetooth App control from starCTRL iOS App.

Improvements

2. Added +/- Green Control to Rainbow Effect

Bug Fixes

Resolved issue from when using Node Mode, some R2 lights stop responding to sACN and Art-Net after reboot.

Known Bugs

4. DMX address above Address 256 does not respond correctly.

V0.7b - VRGB Pixel Mapping Profile Release 2022-11-10

New Features - Big Ones!

- New DMX Profiles for Pixel Mapping Video Files: RGB VW and VRGB Absolute Hue and Relative Colorimetric
- 6. TimoTwo Update over USB
- 7. sACN Priorities Fixtures listen to highest priority sACN
- 8. Extra Dimming Steps to Low End of manual dimming
- 9. Fixture Number Abilities
- 10. Auto Lead/Follow Pairing When paired to a leader, light will auto set to follow
- 11. IP Preset Addresses for easier setting of Static IP

Improvements

- 12. Increased RDM Functionality
- 13. Update RGB White point to 6500K in Profiles 3, 8, 15, 33, 38, 45
- 14. Improved UI on the Color Status Screen.
- 15. Add Page Labels to Wired and Wireless substatus screens
- 16. Updated Output Mode UI to match when changed over DMX

Bug Fixes

- 17. Rainbow Effect at low Intensity shows dark pixels
- 18. When Resetting to default, Effects will be set to Off

Known Bug

19. When using Node Mode, some R2 lights stop responding to sACN and Art-Net after reboot. Current workaround: Disable Node Mode, then enable Node Mode.

V0.6c - Communications Release 2022-01-28

New Features - Big Ones!

- 20. sACN Unicast, Multicast
- Art-Net over Wifi Assign light to connect to a network Client Mode (Update Required Over Wifi)*
- 22. Art-Net over Wifi AP Mode DHCP (Update Required Over Wifi)*
- 23. Node Mode Wired Ethernet in on LAN 1 and DMX out on LAN 2
- 24. RDM implementation for identify, address, profile, pixel count, output mode, status LEDs
- 25. Fixture Substatus Screens Chromaticity, DMX, Wired Network, Wireless Network.
- 26. Output Mode Button Shortcut Hold Enter and Right for 2 seconds
- 27. Bluetooth reset button shortcut Hold Link button for 3 seconds

Improvements

- 28. Firmware Update Process enhanced with status light feedback (With Bootloader 0.9)
- 29. Output from fixture is disabled during firmware update.
- 30. Fixture can exit firmware update using power button.
- 31. Fixture no longer times out of firmware update.
- 32. When changing Effects on DMX, the effects timer is reset to 0
- 33. Press and hold on Profiles scrolls through profiles
- 34. Added the Hue Degrees to the Color Preset
- 35. Min and Max shortcuts enabled on Number of Pixels selection-
- 36. Identify fixture command enabled in CRMX Workshop
- 37. Button shortcut to reset Bluetooth connection.
- 38. Added Wireless DMX and Wifi firmware versions to the Version Screen
- 39. Wireless DMX Settings Menu streamlined.
- 40. Ethernet Settings Menu streamlined.
- 41. Firmware display updated to include all fw installed.
- 42. Chromaticity display to reflect fixture output based on profile chosen
- 43. Wireless button shortcut includes disabling all wireless communications methods
- 44. Visual indicator when fixture is busy processing user input
- 45. Gives Error when Wifi Module is not updated (0.6b)

Bug Fixes

- 46. Fix Reset to Default values to match button shortcuts
- 47. Output Mode control on DMX is not changing UI screen
- 48. Temperature Sensors resets on Wireless DMX resolved

- 49. When Saving DHCP as Static is pressed, It should switch to Static IP mode.
- 50. Display IP address now show static IP address when enabled
- 51. Hue Button Shortcut fixed
- 52. CCT Button Shortcut fixed
- 53. Fixed Bluetooth Status Lights remaining on when disconnected
- 54. Status LEDs reflect correct LEAD/FOLLOW state of fixture
- 55. LEAD fixture no longer needs power cycle to send data
- 56. FOLLOW fixture no longer need power cycle to receive data
- 57. LEAD over wireless Tx speed reduced to improve data processing on Rx fixtures
- 58. Optimized Art-net reception for high universe counts in broadcast settings
- 59. Main display now shows output mode chosen when using wired ethernet protocols
- 60. Main display timeout issue resolved when broadcasting large universe counts
- 61. Fixture reboot when changing wired input settings has been resolved.
- 62. End of Life EVP fixtures
- 63. LED Hours increments fixed (0.6b)

Known Bug

64. Rainbow Effect at low intensities shows a dark stop.

V0.5j - 2021-11-02

Bug Fixes and Improvements

- 1. Fixed Profile 6, 7, 36, 37.
- 2. Improved DMX-able Effect performance.

V0.5i - 2021-09-24

New Features

- 1. xy Control Of the light with new DMX Profiles (19, 20)
- 2. Spectral Fidelity Control of xy Profiles (21, 22)
- 3. On Art-Net, UI screen flashes the Universe number if the lamp is not receiving specified universe

Bug Fixes and Improvements

- 4. When on Art-Net, Added full IP address to Substatus Screen. (Press enter on Status screen to get to the Substatus screen)
- 5. Screen UI addition of "NO" for Normal Output mode
- 6. Resolved Excessive ArtPoll requests reboot when Using Art-Net
- 7. When Saving DHCP as Static is pressed, it should switch to Static IP.

- 8. Changing Profiles Should not change manual mode Output.
- 9. Hue Button Shortcut Fixed

Known Issues

- 10. Profile 7, 8, 37, 38 are not functioning.
- 11. Built in Effects are showing degraded performance.